

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG 1




FIG 2A




FIG 2B




FIG 3A




FIG 3B





FIG 3C



Applicant(s): Michael N. Perugini, Gary D. Eastman, Alfred J. Langon, Raymond A. Prew, Erol D. Saydam
HIGH SPEED, HIGH DENSITY INTERCONNECTION DEVICE

FIG 4A




FIG 4B




FIG 5A




FIG 5B




FIG 5C




FIG. 6




FIG. 7

14




FIG. 8




FIG. 9




FIG. 10




FIG. 11

